

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 1 of 6
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/16/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03WW_011MH	Test ID: S1032-022009	Notifications (Residents, Fire, 311) : Yes



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 2 of 6
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/16/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03WW_011MH	Test ID: S1032-022009	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Downspout Connection; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 3 of 6
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/16/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03WW_011MH	Test ID: S1032-022009	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Main Sewer; Smoke: Heavy; Status: Public ROW

Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 6
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/16/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03WW_011MH	Test ID: S1032-022009	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Main Sewer; Smoke: Heavy; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Main Sewer; Smoke: Heavy; Status: Public ROW


Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 5 of 6
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/16/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet : _	Supervisor : John Daly
Manhole ID: S03WW_011MH	Test ID: S1032-022009	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Catch Basin; Smoke:

Medium; Status: Public ROW


Landscape



Defect



ID



Location: N/A; Type: Storm Manhole; Smoke:

Medium; Status: Public ROW

Landscape





City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 6 of 6
Sewershed : Gwynn Falls	Company : <u>URS</u>	Date: 09/16/2008
Test to be Performed : Smoke : X Dyed Water :	Ground Condition : Dry : X Damp : Wet :	Supervisor : John Daly
Manhole ID: S03WW_011MH	Test ID: S1032-022009	Notifications (Residents, Fire, 311) : Yes

ID



Location: N/A; Type: Catch Basin; Smoke:

Heavy; Status: Public ROW

Landscape



